

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Spring 2013 Levee Inspection Results

Eastern Honcut Creek

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

*
SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2013 Levee Inspection Results

Eastern Honcut Creek

Waterway			Bank	Unit Miles
Unit No. 01 Van Tress			Left	1.50
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	04/16/2013 - 04/16/2013			
DWR Inspector	Rick Burnett			
Accompanied By				

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2013

Eastern Honcut Creek

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 01 Van Tress				Left	1.50	04/16/2013 04/16/2013	Rick Burnett	

LMR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1				Emergency Supplies & Equipment	LS	A Ma		°	°	6
DWR ID: DWR_NA0006_01_s_2013_6										
2				Flood Preparedness & Training	LS	M Ma		°	°	9
DWR ID: DWR_NA0006_01_s_2012_9										
3				Operations & Maintenance Manuals	LS	M Ma	Inspector Comments: No manual was available during the inspection.	°	°	10
DWR ID: DWR_NA0006_01_s_2012_10										
4	0.00	0.08		Vegetation	CR	M Ma	V1 : Control annual grass and weeds on the levee slopes and easements.	°	°	2
DWR ID: DWR_NA0006_01_s_2013_2										
5	0.01	1.50		Vegetation	LS	M Ma	V2 : Remove the wild growth other than native grasses from the levee slopes.	39.298521 ° -121.569497 °	39.295267 ° -121.546559 °	1 Y
DWR ID: DWR_NA0006_01_s_2012_1										
6	0.05	1.50		Vegetation	WS	M Ma	V2 : Remove the wild growth other than native grasses from the levee slopes.	39.298849 ° -121.569419 °	39.295267 ° -121.546560 °	3 Y
DWR ID: DWR_NA0006_01_s_2012_3										
7	0.66	1.19		Encroachments	WS	M En	DT : Ditch	39.297661 ° -121.558334 °	39.295134 ° -121.551805 °	5 Y
DWR ID: DWR_NA0006_01_s_2012_5										
8	0.68	1.46		Encroachments	LS	M En	DT : Ditch	39.297480 ° -121.558325 °	39.295261 ° -121.546759 °	8 Y
DWR ID: DWR_NA0006_01_s_2012_8										

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2013

Eastern Honcut Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Van Tress	Left	1.50	04/16/2013 04/16/2013	Rick Burnett

Levee Mile Report Line	5
Start Levee Mile	0.01
End Levee Mile	1.50
Location	Land Side
Category	
Item	Vegetation
This photo shows the landside of the levee at levee mile 0.10.	
jhirabay_s_20130314_033.JPG	



Levee Mile Report Line	6
Start Levee Mile	0.05
End Levee Mile	1.50
Location	Water Side
Category	
Item	Vegetation
This photo shows the waterside of the levee at levee mile 0.10.	
jhirabay_s_20130314_034.JPG	



Levee Mile Report Line	7
Start Levee Mile	0.66
End Levee Mile	1.19
Location	Water Side
Category	
Item	Encroachments
Toe ditch parallel to levee @ w/s toe. Heavy vegetation in ditch.	
jhirabay_s_20130314_035.JPG	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2013

Eastern Honcut Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Van Tress	Left	1.50	04/16/2013 04/16/2013	Rick Burnett

Levee Mile Report Line	8
Start Levee Mile	0.68
End Levee Mile	1.46
Location	Land Side
Category	
Item	Encroachments

Levee mile 0.85, this photo is looking upstream at a ditch on the landside toe.

jhirabay_s_20130314_036.jpg



* Location	** Rating	+ Issue Type
LS : Land Side	A : Acceptable	Ma : Maintenance Deficiency
WS : Water Side	M : Minimally Acceptable	Ob : Design & System Obsolescence
CR : Crown	N : Not Inspected/Rated	En : Enforcement
	C : Corrected	
	A/W : Acceptable but Monitor & Maintain	
	U : Unacceptable	